

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-001833**Date Inspected:** 18-Mar-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 1800**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 630**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

<b>CWI Name:</b>	N/A	<b>CWI Present:</b>	Yes	No			
<b>Inspected CWI report:</b>	Yes	No	N/A	<b>Rod Oven in Use:</b>	Yes	No	N/A
<b>Electrode to specification:</b>	Yes	No	N/A	<b>Weld Procedures Followed:</b>	Yes	No	N/A
<b>Qualified Welders:</b>	Yes	No	N/A	<b>Verified Joint Fit-up:</b>	Yes	No	N/A
<b>Approved Drawings:</b>	Yes	No	N/A	<b>Approved WPS:</b>	Yes	No	N/A
				<b>Delayed / Cancelled:</b>	Yes	No	N/A

**Bridge No:** 34-0006**Component:** Macro Etch Samples**Summary of Items Observed:**

On this date, Caltrans Office of Structural Materials (OSM), Quality Assurance (QA) Inspector, David A. Smith was present for the observations related the following;

During the evening shift this Caltrans QA Inspector did photograph three lots of Macro Etched Samples. The three sample lots were Deck Panel DP-008/DP-299-001, DP-039-001 and DP-044-001. The photographs for these Macro Etched Samples were placed in folders in the "Shared Docs on Team China Server" under Team OBG. The folder within this Team OBG is named "Macro Etched Samples" where the rest of the folders are kept by the date they were photographed. Each of the Macro Etched Samples was photographed once in an over all view and if an indication existed then a close up photograph was taken to show this indication.

**Summary of Conversations:**

There were no pertinent conversations pertaining to the project during this shift.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

**Inspected By:** Smith,David

Quality Assurance Inspector

**Reviewed By:** Hager,Craig

QA Reviewer